

INSPECTION ALERT

Due to a production irregularity, catalytic converters produced by Walker Manufacturing Company before January 26, 2009 have labels with an extra zero added to its Executive Order (E.O.) number. Regular labels have the E.O. marked as D-182-XX, while the irregular ones have the E.O. marked as D-182-0XX. Executive Orders affected are: D-182-37, D-182-38, D-182-39, D-182-40, D-182-41, D-182-42, D-182-43 and D-182-44.

This labeling irregularity does not affect the performance of the catalytic converters, nor should it render the catalytic converters non-compliant or illegal during a Smog Check inspection. When verifying such E.O.s on ARB's database, please do not input the extra "0"..Instead, type in the regular E.O. number to access a copy of the specific Executive Order in the database.